

407-645-5008 Interplanllc.com

February 2nd, 2022

Reference: Food Lion #2839

860 PARRIS ISLAND GTWY BEAUFORT, SC 29906

IP # 2021.1218

This letter is to inform the contractor of deficiencies which must be corrected as per Crescent Electrical Survey. Refer to Crescent Survey and to the Construction Documents for additional information.

Deficiency D-1 Panel Schedule Labeling

Location: Entire Store

Description: all schedules are to be 100% accurate, on card stock, typed,

dated, and installed in a clear pocket. ec shall go through all

existing electrical panels to trace and verify all circuits for accuracy. receptacles and lighting are to be labeled by area/location. sales floor lighting circuits are to include row number. case circuits are to reference refrigeration circuits. spare is a breaker with no wire. blank

is an empty slot. all wired and active breakers shall be properly scheduled. note: wired breakers with no active load / device shall be labeled as spare, ending location. do not remove existing panel schedules. electronic copies of all panel schedules are required

at closeout.

Response: See sheets E6.01.

Deficiency D-3 Refrigeration Circuit Sizing

Location: Entire Store

Description: entire store/engineer to size main breakers / conductors per MOCP

/ MCA requirements in revised refrigeration summary, see

disconnect inventory for relative data.

Mt2 / rack b: 300-amp fuses, 350 kcmil cu. Lt1 / rack c: 400-amp fuses, (2) 250 kcmil cu. Mt1 / rack a: 500-amp fuses, 600 kcmil cu

. **all roof top condensers are fed from the racks**

Ac 1: 175-amp breaker, 4/0 cu.

Ac 2: 350-amp breaker, 350 kcmil cu.

Response: See sheet E6.04.



#1175 February 22, 2021 Page 2 of 5

Deficiency D-14 Emergency Lighting Along with Select Night Lighting

Location: Entire Store

Description: Currently fed from Panel EM. New emergency lighting and night

lighting systems to be designed by engineer.

Response: See sheet E1.01.

Deficiency D-16 Existing Neutrals, Case Lighting & Fans

Location: Mechanical Room

Description: Existing refrigeration circuits in mechanical room suggest lights and

fans are sharing neutrals. This only applies to new and relocated case work; Lights and fans both are to have dedicated neutrals.

Response: See sheet E6.01.

Deficiency D-17 Double Terminations: Remove

Location: Mechanical Room

Description: The following panels have double terminations:

BD; Circuit 31. H; Circuit 22.

Repair, branch circuit panelboards are not to be used as junction

boxes, remove all additional wiring, single terminations only.

Response: See sheet E6.01.

Deficiency D-19 Grinder - Repair

Location: Meat prep

Description: Replace damaged male / female plug and boots.

Response: See sheet E1.02.

Deficiency D-22 Install Egress Lighting (7)

Location: Engineer to verify number with final fixture plan

Description: entire store **Response:** See sheet E1.01.

Deficiency D-32 Panel BDM Data

Location:Deli Bakery storageDescription:Schedule Incorrect.Response:See sheet E4.01.



#1175 February 22, 2021 Page 3 of 5

Deficiency D-33 Panel BD Data

Location: Deli Bakery storage **Description:** Schedule Incorrect. **Response:** See sheet E4.01.

Deficiency D-34 Dock/Main Gear (4 SECTIONS)

Location: Mechanical room **Description:** vacuum & wipe clean

Response: See sheet E6.04.

Deficiency D-35 Panel F Data; Schedule Incorrect

Location: POS Room

Description: Schedule Incorrect. **Response:** See sheet E6.01.

Deficiency D-36 Panel POS Data; Schedule Incorrect

Location: POS Room

Description: Schedule Incorrect. **Response:** See sheet E6.01.

Deficiency D-39 Panel EM Data: Schedule Incorrect

Location: Mechanical Room
Description: Schedule Incorrect.
Response: See sheet E6.01.

Deficiency D-41 Panel D-1 Data; Schedule Incorrect

Location:Mechanical RoomDescription:Schedule Incorrect.Response:See sheet E6.01.

Deficiency D-42 Panel H Data; Schedule Incorrect

Location:Mechanical RoomDescription:Schedule Incorrect.Response:See sheet E6.01.

Deficiency D-43 Panel E Data; Schedule Incorrect

Location:Mechanical RoomDescription:Schedule Incorrect.Response:See sheet E6.01.



#1175 February 22, 2021

Page 4 of 5

Deficiency D-44 Panel B Data; Schedule Incorrect

Location:Mechanical RoomDescription:Schedule Incorrect.Response:See sheet E6.01.

Deficiency D-45 Panel A Data; Schedule Incorrect

Location: Mechanical room
Description: Schedule Incorrect.
Response: See sheet E6.01.

Deficiency D-46 Panel J Data; Schedule Incorrect

Location:Mechanical roomDescription:Schedule Incorrect.Response:See sheet E6.01.

Deficiency D-48 Panel D-2 Data; Schedule Incorrect

Location: Mechanical room
Description: Schedule Incorrect.
Response: See sheet E6.01.

Deficiency D-50 Panel G Data: Schedule Incorrect

Location:Mechanical roomDescription:Schedule Incorrect.Response:See sheet E6.01.

Deficiency D-52 A #8; Circuit Overload

Location: Mechanical room

Description: 19.2 amps on a 20-amp circuit, 10 AWG, labeled as LTS-

register. Repair; install an additional 20-amp branch circuit

and split the load to 16 amps or less.

Response: See sheet E6.01.

Deficiency D-53 Panel R, MT 2 Fuse Frame; Hot A Phase Finger Mechanism (Monitor

Issue)

Location: Mechanical Room

Description: Issue with A Phase is 136 F, which is 16 F over a normal

B Phase. Room Temp 90 F

Response: See sheet E6.04.

Deficiency D-55 Panel C-1 Data; Schedule Incorrect



#1175 February 22, 2021 Page 5 of 5

Location:Mechanical roomDescription:Schedule Incorrect.Response:See sheet E6.01.

Deficiency D-56 Panel C-2 Data; Schedule Incorrect

Location: Mechanical room
Description: Schedule Incorrect.
Response: See sheet E6.01.

Deficiency D-58 Electrical Repair Notes; Add To The Prints:

Location: Mechanical Room

Description: General Electrical Notes, Add or Change All distribution sections,

branch panels, main breakers & disconnects shall have phenolic

labels, (1 & 1/2" black on white). Main breaker and safety

disconnect labeling shall match. Arc Flash Labels and mechanical

drawings will dictate naming Labels can be ordered from CD

Controls the national account breaker supplier. - Review all existing

single pole breaker sizing, correct as needed per code and

equipment nameplate

. **Response**: See sheet E6.04.